

Message

From: Harrington, Jim (DEC) [jim.harrington@dec.ny.gov]
Sent: 5/20/2015 7:40:31 PM
To: Garbarini, Doug [Garbarini.Doug@epa.gov]
Subject: FW: Revised OU2 Groundwater Samplings December2014 and March 2015
Attachments: OU2 1,4Dioxane Groundwater Samplings December 2014 and March 2015.pdf; OU2 Groundwater Sampling March 2015.pdf

Doug – attached figures – Navy had changed the order and Henry didn't notice. Jim H

James B Harrington, PE
Director, Remedial Bureau A
Division of Environmental Remediation
518 -402-9624

Please note my new email address
Jim.Harrington@dec.ny.gov

From: Wilkie, Henry (DEC)
Sent: Wednesday, May 20, 2015 1:04 PM
To: Harrington, Jim (DEC)
Subject: RE: Revised OU2 Groundwater Samplings December2014 and March 2015



Jim,
Here are the revised figures showing RE105D1 (540') and RE105D2 (740').

Henry Wilkie

Henry Wilkie

Environmental Engineer I, Division of Environmental Remediation

New York State Department of Environmental Conservation
625 Broadway, Albany, New York 12233-7015
P: (518) 402-9622 | F: (518) 402-9627 | henry.wilkie@dec.ny.gov

www.dec.ny.gov |  | 

From: Harrington, Jim (DEC)
Sent: Tuesday, May 19, 2015 10:14 AM
To: Wilkie, Henry (DEC)
Subject: RE: Revised OU2 Groundwater Samplings December2014 and March 2015

Henry – thanks – I spoke with Doug G from EPA – several of the wells (103, 105) show shallower depths on what should be deeper wells – for example RE105D1 is listed at 740' and RE105D2 is listed at 540' – that doesn't seem right. Please check all of the depths to make sure that they are correct. thanks Jim H

James B Harrington, PE
Director, Remedial Bureau A
Division of Environmental Remediation

518 -402-9624

Please note my new email address

Jim.Harrington@dec.ny.gov

From: Wilkie, Henry (DEC)

Sent: Friday, May 15, 2015 10:42 AM

To: Harrington, Jim (DEC)

Cc: Evans, Daniel (DEC); Swartwout, John (DEC); Scharf, Steven (DEC)

Subject: Revised OU2 Groundwater Samplings December2014 and March 2015

Jim,

I revised the figure, after the Navy found out that the monitoring well identifications for TT101D, TT101D1 and TT101D2 were incorrectly assigned to sample IDs during the March 2015 field collection.

Henry